MATERIAL SAFETY DATA SHEET
Conforms to
OSHA Hazard Communication Standard 29CFR 1910, 1200

PRODUCT IDENTIFICATION

Trade Name: CSXG

Generic Name:

Manufacturer's Name: West Sioux Ceramics/Dakota Potters Supply

CAS Number: Mixture (see below)

Address: 2315 West Madison Street

Phone Number (Emergency): (605) 332-1946

City: Sioux Falls, SD

State:

Zip: 57104

I. PRODUCT INGREDIENTS

CHEMICAL AND/OR COMMON NAME	CAS NUMBER
Goldart, OM4	14808-60-7 and 13463-67-7
Greenstripe	1332-58-7
Hawthorne	14464-46-1; 14808-60-7;1344-28-1;134763-67-7
Red Art	14464-46-1; 15468-32-3; 14808-60-7
48 mesh Grog	12269-78-2;14808-60-7;12183-80-1
Manganese dioxide powder	7439-96-5;1309-37-1;1344-28-1;1304-28-5
30 mesh Grog	12269-78-2;14808-60-7;12183-80-1

II. PHYSICAL DATA

Boiling Point	Vapor Pressure	Specific Gravity	Melting Point
N/A	N/A	N/A	2350 degrees
Solubility in Water	**Vapor Density (Air-1)**	**Percent Volatile**	**Evaporation Rate**
Nil	N/A	N/A	N/A.

Appearance and Odor:
Red when moist; light-brown color when fired.

III. FIRE AND EXPLOSION DATA

Flash Point:	Flammable Limits	LEL:	UEL:
Nonflammable & Non-explosive	Non-flammable	N/A	N/A

Extinguishing Media: N/A

Special Fire-fighting Procedures: None.

Unusual Fire or Explosion Hazards: None.

IV. HEALTH HAZARD INFORMATION

HAZARD BY ROUTES OF EXPOSURE (Indicate Chronic and Acute)

Inhalation: Repeated, prolonged inhalation of dust may cause delayed lung injury (Silicosis); effects aggravated by smoking.

Ingestion: N/A.

Eye: N/A	Health: 2*	Flammability: 0
Skin Contact/Absorption: N/A	Reactivity: 0	Pers. Protection: E

Signs and symptoms Associated with Exposure over TLV:

Short Term: Shortness of breath, coughing associated with inhalation of dust

Long Term: May cause Silicosis, a chronic disease of the lungs marked by acute fibrosis.

Medical Conditions which may be Aggravated:

Emphysema, Silicosis, Chronic Bronchitis, or other respiratory disorders.

Any of Part I Listed as Carcinogens: (NTP, IARC, OSHA:

No.

V. HEALTH HAZARD INFORMATION

EMERGENCY/FIRST AID PROCEDURES

Inhalation: If use conditions generate airborne contamination, the material should be handled in an open ventilated area. Where adequate ventilation is not available, use NIOSH-approved dust masks or respirators with dust, mist and fume filter to reduce exposure. Where exposure potential under the use conditions necessitates a higher level of protection, use a positive-pressure, air-supplied respirator.

Ingestion: All food should be kept in separate area away from the storage and use location. Eating, drinking and smoking should be prohibited in areas where there is a potential for significant exposure to this material. Before eating, hands and face should be thoroughly washed.